APPENDIX A: Phase I - Building #1



Photograph 1.:



Photograph 2.:




Photograph 3.:



Photograph 4.:



Photograph 5.:




Photograph 6.:



Photograph 7.:



Photograph 8.:



Photograph 9.:



Photograph 10.:



Photograph 11.:



Photograph 12.:



Photograph 13.:



Photograph 14.:



Photograph 15.:



Photograph 16.:

APPENDIX B: Phase I - Building #2



Photograph 1.:



Photograph 2.:



Photograph 3.:



Photograph 4.:



Photograph 5.:



Photograph 6.:



Photograph 7.:




Building Envelope Consultants and Scientists, LLC 6339 Ten Oaks Road, Suite 307, Clarksville, MD 21029 410-531-3200 | www.becsmd.com



Photograph 8.:



Photograph 9.:



Photograph 10.:

Unit 121



Photograph 11.:

Unit 121



Photograph 12.: Unit 121 APPENDIX C: Phase I - Building #3



Photograph 1.:



Photograph 2.:



Photograph 3.:



Photograph 4.:



Photograph 5.:



Photograph 6.:



Photograph 7.:



Photograph 8.:



Photograph 9.:



Photograph 10.:



Photograph 11.:



Photograph 12.:



Photograph 13.:



Photograph 14.:



Photograph 15.:



Photograph 16.:



Photograph 17.:



Photograph 18.:




Photograph 19.:



Photograph 20.:



Photograph 21.:



Photograph 22.:

APPENDIX D: Phase I - Building #4



Photograph 1.:



Photograph 2.:



Photograph 3.:




Photograph 4.:



Photograph 5.:



Photograph 6.:



Photograph 7.:



Photograph 8.:



Photograph 9.:



Photograph 10.:



Photograph 11.:




Photograph 12.:



Photograph 13.:



Photograph 14.:





Photograph 17.: Unit 171